

Richard F. Klenk, Manager, Plant & Structures Division, JFK1A  
 Harry R. Pool, Jr.  
 June 10, 1982

Subject: USE OF ASBESTOS IN PORT AUTHORITY FACILITY BUILDING  
 CONSTRUCTION

Reference: Memo, R. F. Klenk to H. R. Pool, Jr., 4/23/82, same subject  
 Memo, H. Pool, Jr. to R. F. Klenk, 4/16/82, same subject

By: W. Connell, L. Halley, P. Nicholson, C. Vasquez

Rec'd To	Date	Indexed	File

Pursuant to your request, the following is a list of Port Authority buildings at the indicated facilities which may contain asbestos spray-on fireproofing:

→ John F. Kennedy International Airport  
 Control Tower  
 Police Emergency Garage  
 Police Satellite Garage  
 Central Heating Plant  
 Police Building  
 Port Authority Administration Building

→ La Guardia Airport  
 Central Terminal Building  
 Marine Air Terminal  
 Hangar Seven  
 Police Emergency Garage  
 Automotive Garage

*Contracts in Design*

→ Newark International Airport  
 North Terminal Building  
 Heating Plant  
 Buildings 5, 10, 11, 33 and 88

Holland and Lincoln Tunnels  
 Administration Buildings  
 Maintenance Garages  
 Vent Buildings

George Washington and Staten Island Bridges  
 Administration Buildings  
 Toll Houses  
 Maintenance Building (Goethals Bridge)

Port Authority Marine Terminals

New York

Administration Building and Maintenance Garage  
 Passenger Ship Terminal

New Jersey

Building 110  
 Sign Shop  
 Central Automotive and Stock  
 Administration Building

ENG	JJH	SP	RT	AW



George Washington Bridge Bus Station  
Bus Station  
East Building  
Ventilation Building

World Trade Center  
Tower A - Zone 1 and limited areas of the subgrade

Port Authority Bus Terminal  
Main Building constructed before 1973

Port Authority Trans-Hudson  
Shops at Waldo, Henderson, Pavonia and Hoboken  
Newark Station

Additions may have to be made to the foregoing list. Generally any building constructed prior to 1973 is a suspect asbestos containing building. Because the Environmental Protection Agency in 1973 issued a ban on the use of spray-on fireproofing with asbestos, as a guide, all buildings constructed subsequent to that date may be considered as not containing this material.

The above locations are Port Authority owned structures. This listing does not include all structures where Port Authority personnel may work.

If you have any questions we will be happy to discuss them with you.

*Harry Pool*

Harry R. Pool, Jr., Supervisor  
Environmental Protection  
Risk Management Division

HRP/daw